




How to Format VirtualLab Fusion Results

Abstract




While providing handy tools to obtain fast and accurate results for a desired optical task is the main purpose of any optical simulation software, the value of a versatile post processing should not be underestimated. The adaption of the appearance of the resulting data enables to either fit specific requirements for a publication in a journal or reports, but moreover to emphasize and highlight interesting aspects of the results. In this Use Case different options for the customization of detector results in VirtualLab Fusion are demonstrated. These tools can be utilized for usual 2D field representations, but also for 1D cross-sectional data and multi-graphs.

This Use Case Shows





How to customize 1D and 2D figures in VirtualLab Fusion.

Color Schemes




In the tab *Manipulations* of the menu ribbon, the user can choose from a selection of different color schemes for the depiction of 2D data. It is also possible to adapt the existing schemes or to define a customized ones.




Marker Colors
can also be
defined per
color table.


Logarithmic & Exponential Color Tables




Examples for Color Schemes




Reverse Rainbow



Astro Colors




Hot Colors



Black & White

Scaling and Axis Configuration



Property Browser

4: SSTF Setup

View Object Selections

- General
 - Window Size 600, 600
 - Zoom Factor (2.0816E+05; 1875)
 - Zoom Factor Unit X 1 px / [1 ns]
 - Zoom Factor Unit Y 1 px / [1 mm]
- Colors
 - Color Table Tricolor
- Data
 - Auto Scaling of Data False
 - Displayed Data Range [0 V/m; 33.8 V/m]
 - Field Quantity Amplitude
 - Format of color scale Engineering
 - Interpolated View True
- Labels
 - Font Size of Axis Labels 12
 - Font Size of Title 12
- Selection (General)
 - Selection Mode Rectangle or Ellipse
- Selection (Line)
 - Display Line Marker False
- Selection (Point)
 - Display Point Marker False
- Selection (Region)
 - Show Rectangle or Ellip False
- View Mode
 - 3D Mode False



Format of y-Axis

Format of the y-Axis values

In the *Property Browser* the user can configure various parameter like the size of the overall window and the used fonts. Moreover, the displayed data range of the color scheme can be adjusted here.

All these parameters can be pre-set in the *Global Options*.


Configuration of Axes



Furthermore, parameters like the format of the axes and the minimum number of displayed ticks can be adapted. For the format of the axes, three different options are available:

- *Standard*: The numbers are shown as usual.
- *Scientific*: Powers of ten are used to make to highlight the magnitude and to reduce the number shown zeros.
- *Engineering*: SI prefixes are used to reduce the displayed zeros.

Coordinate and Interpolation Settings



Edit Coordinate and Interpolation Settings

x-Axis

Description 1 Measured Time

Physical Property Time

Interpolation Method Cubic 4 Point

Dimensions

Sampling Distance 1.5712 fs

Positioning

Start Coordinate 3 0 s

y-Axis

Description 2 X

Physical Property Length

Interpolation Method Cubic 4 Point

Dimensions

Sampling Distance 1.6393 μm

Positioning

Center Around Zero 4 0

Extrapolation Mode: Zero

Outside Values are Zero

OK Cancel Help


Coordinate and Interpolation Settings

Edit Subsets



Array - Array Operations

More advanced options for the control of the axes are provided by the *Coordinate and Interpolation Settings*, which can be found in the *Manipulations* menu. Here, the user can rename the axes, change the physical unit and adjust the sampling according to the requirements.


Point and Rectangle Markers




Point, Line and Rectangle or Ellipse Markers can be found in the *View* tab to select specific parts of the result data for further investigation.



If e.g. a *Rectangle Marker* is applied, new options will appear like the ability to zoom directly into the selected area.



1D Cross-Sectional Selection / Line scan



The screenshot shows the 'Settings for the Line Extraction' dialog box and the 'Selection Related Operations' menu. The dialog box has the following settings:

- No. of Data Points to Extract: 1170
- Interpolation Method for Extraction: ☒ Method of Source Array, ☐ Nearest Neighbor / Constant Interval
- Parameters of Result:
 - New Axis Description: Time
 - New Physical Property of Axis: Time
 - New Interpolation Method: Cubic 4 Point
- New Coordinate Positioning: Center Around Zero



The 'Selection Related Operations' menu is open, showing the following options:

- Fill Rectangular Selection
- Clear Rectangular Selection
- Clear Inverse of Rectangular Selection
- Extract Rectangular Selection
- Extract Equidistant 1D Data Along Selected Line
- Extract Subset Data at One Point
- Extract Cross Profile at Point
- Normalize According to Rectangular Selection
- Remove Phase Dislocations in Rectangular Selection

A red arrow points to the 'Extract Equidistant 1D Data Along Selected Line' option in the menu.

If a *Line Marker* is applied, the corresponding 1D array will displayed right below the initial document. With the option *Extract Equidistant 1D Data Along Selected Line* an individual document can be created.

1D Cross-Section Visualization Options



In case of 1D data, the *Property Browser* provides similar options as for 2D data. The option *Is Description User-Defined* enables the user to define a custom description of the y-axis.

Lines and Symbols of 1D Graphs

Property Browser

11: 2D Cut

View Object Selections

Lines and Symbols

Line Color ■ Blue

Line Thickness 2

Symbol Shape <No Symbol>

Use Smoothed Graphs True

Selection (General)

Selection Mode Range

Selection (Point)

Display Point Marker False

Selection (Range)

Display Range Marker False

X-Axis

Description Measured Time

Descending Coordinate False

Coordinate Range [-1.4132 ns; 3.2801 μ s]

Format Engineering

Logarithmic Scaling False

Minimum Number of 1 2

Y-Axis

Data Range [531.05 μ V/m; 33.777 V/m]

Description Amplitude


Is Description User-Def True

Format Engineering

Logarithmic Scaling False

Read Labels from Inside True

Lines and Symbols



Lines and Symbols

Line Color ■ Red


Line Thickness 5

Symbol Color ■ Red

Symbol Scaling Factor 1.5

Symbol Shape Filled Square

Use Smoothed Graphics True



Lines and Symbols

Line Color ■ Gray


Line Thickness 2

Symbol Color ■ Black

Symbol Scaling Factor 1

Symbol Shape Dot

Use Smoothed Graphics True



Lines and Symbols

Line Color ■ DarkKhaki


Line Thickness 5

Symbol Shape <No Symbol>


Use Smoothed Graphics True

In case of 1D data, it is possible to utilize symbols to indicate the actual sampling points in the curve. Their appearance can be adjusted in the *Property Browser*.



Generation of a Multigraph Document



Multiple *1D Cross-Sections* can be combined to one document in the *Manipulations* tab:





Note: The option *Copy View Settings* allows for an easy duplication of the appearance of two windows.



Note: *Multigraph Mode* needs to be active to see both results simultaneously

Formatting of a Multi-Graph Document



Change Subset Parameters

Append Subset(s) from Another Data Array

Delete Subset(s)


Extract Subset(s)

Sum all Subsets

Change Subset Parameters

Subset #	Description	Physical Property	Precision
1	Cross-Section At Center	Electric Field Strength	Double Precision
2	Cross-Section At Border	Electric Field Strength	Double Precision

OK Cancel Help



Configuration of the Subset Graphs per y-Axis

Subset #	Description	Physical Property	Ordinate	Color	Symbol
1	Cross-Section At Center	Electric Field Strength	Left-Hand	Blue	•
2	Cross-Section At Border	Electric Field Strength	Left-Hand	Red	x


☐ Synchronize Settings

The configuration is valid.

OK Cancel Help

With *Change Subset Parameters* in the *Manipulations* tab the basic properties of each individual subsets (such as the name and displayed physical quantity) can be set, while *Subset Settings* in the *View* tab allows for a customized visualization (like e.g. color).

Formatting of a Multi-Graph Document



Property Browser

16: Comparison

View Object Selections

Use Smoothed Graph **True**

▼ **Multigraph Options**

Multigraph Mode **True**

Legend Visible **True**

Legend Alignment **Top Right**

▼ **Selection (General)**

Selection Mode **Range**

▼ **Selection (Point)**

Display Point Marker **False**

▼ **Selection (Range)**

Display Range Marker **False**

▼ **X-Axis**

Descending Coordinate **False**

Coordinate Range **[2 μ s; 7 μ s]**

Format **Scientific**

Logarithmic Scaling **False**

Minimum Number of **2**

▼ **Y-Axis Left-Hand**

Data Range **[958.93 μ V/m; 33.751 V/m]**

Description **Amplitude**

Is Label User-Defined **True**

Color **Black**

Format **Engineering**

Logarithmic Scaling **False**

Read Labels from Ins **True**

Legend Alignment

Where shall the legend be positioned?

Similar to the previous cases, the *Property Browser* allows for certain adjustments. In this case, however, it is also possible to adjust the visibility and position of the legend.

Document Information

title	How to Format VirtualLab Fusion Results
document code	MISC.0094
document version	1.0
software edition	VirtualLab Fusion Basic
software version	2021.1 (Build 1.180)
category	Feature Use Case
further reading	